


CBR1000F (E)



- 1. 12V BATTERY
- 2. MAIN FUSE
- 3. IGNITION SWITCH
- 4. HEADLIGHT
- 5. TAIL LIGHT
- 6. HORN
- 7. STARTER MOTOR
- 8. ENGINE TEMPERATURE SENSOR
- 9. OIL PRESSURE SENSOR

WIRING COLOR CODE

RED	BLACK	GREEN	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE
GREEN	RED	BLACK	YELLOW	BLUE	ORANGE	PINK	WHITE

0030Z-MZ2-6000