


Odometer/Tripmeter/Coolant temperature meter

The display (1) has three functions: odometer, tripmeter and coolant temperature meter.


Push the button(2) to select “ODO” (Odometer), “TRIP” (Tripmeter) and “TEMP” (Coolant temperature meter) mode.

To reset the tripmeter, push and hold the button when the display is in the “TRIP” mode.




- (1) Multi-function display
- (2) Multi-function select and reset button


ODO



TRIP



TEMP



Tripmeter
reset

