

CT90K6

COMPARISON OF CT90K6

1. FUEL COCK

The indication marks and their positions on the fuel cock was changed to a new type.




Fig. K6.1 ① Fuel cock ② Lever

2. HEADLIGHT AND ENGINE STOP SWITCH

The dimmer switch, previously offered on the switch housing at the right side of the handlebar, was relocated to the left switch housing. This also necessitated changes in the design of the switch housing.




Fig. K6.2 ① Headlight switch ② Engine stop switch